


Lithichrome HILITE . . .

As with Shadow, Hilite is in use throughout the U.S. and Canadian monumental industry for whitening flashed panel inscriptions and carvings on all kinds and colors of polished granites. The great majority of shop mechanics have become so proficient in the applying of Hilite that it cannot be distinguished from the finest "steeled" effects. Applied as intended, Hilite has no visible form of coloration apparent to the eye, even when viewed closely. (Write for brochure . . . How to Spray Hilite and Shadow.) Hilite is so extremely fine in particle size that, when bonded into the sub-pores of granite, weathering has remarkable little effect upon it.



Lithichrome PERMABOND . . .

PERMABOND is a clear Shadow or Hilite—its function being to reduce the color tone of any Hilite or Shadow without any reduction in bonding strength. Shadow, as made, is right for the great majority of uses but occasionally less contrast is desirable. Hilite should require no Permabond for a perfect transparent effect but a new user might add some Permabond until he becomes familiar with using the Airmite. It also can be used as a light "overcoat" for a Shadow Lithipicture as added protection.

Lithco SOLVENT . . .

For cleaning Airmite or airbrush or for removing Hilite, Shadow or Lithco Color (if necessary). This solvent will also dissolve Stoneweld IF USED BEFORE IT HAS HARDENED. Lithco Solvent is the thinner for Lithco Colors if any thinning is needed for spraying. Hilite and Shadow require no thinning for perfect spraying. NOTE: This is the only solvent, except some highly flammable, which will keep the Airmite airbrush in tip-top condition. Flush after each use and the Airmite will always be ready for use. The easy way is to place the Airmite (after use) in a closed vessel containing Lithco Solvent. Have enough solvent in vessel to cover nozzle and material tube only. If this is done, no flushing is necessary. Gasoline or naphtha are of no value for cleaning the Airmite, as they will not dissolve Hilite or Shadow.

